

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: Bopco, L.P.	Contact: Tony Savoie	
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.: (575) 887-7329	
Facility Name: PLU 420 Tank Battery – Release 2	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No.: 30-015-39795

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	25S	31E	700	South	1300	East	Eddy

Latitude: N 32° 5' 45.94" Longitude: W 103° 46' 42.24"

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 135 bbl	Volume Recovered: none
Source of Release: ½" valve on the free water knockout	Date and Hour of Occurrence: 9/9/14 time unknown	Date and Hour of Discovery: 9/9/14 @ ~ 12:50 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104 and BLM	
By Whom? Tony Savoie	Date and Hour: 9/10/14 @ ~ 12:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
Depth to Water. ~310 ft bgs		
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* It appeared that a cow kicked the valve handle on the ½" valve to the open position. The valve was shut and handle removed. The area will be completely fenced off after the remediation is completed.		
Describe Area Affected and Cleanup Action Taken.* All of the fluid soaked into the ground. The spill affected approximately 15,400 sq. ft. around the process equipment earthen containment and well pad area. The release impacted an area previously reported; reference 2RP-2250. Contaminated soil was excavated and hauled to state approved facility for disposal and the excavation backfilled with clean soil. The spill area has been cleaned up in accordance to the NMOCD and BLM remediation guidelines		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brad Blevins	Approved by District Supervisor:	
Title: EHS Asst. Remediation Foreman	Approval Date: 11/18/2014	Expiration Date: NA
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-30-14 Phone: (432) 214-3704	FINAL	

* Attach Additional Sheets If Necessary

2RP-2487