

Received 11/14/2014

NMOCD Artesia

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Avenue, Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141

Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form**Release Notification and Corrective Action****OPERATOR**☐

Initial Report

☒


Final Report

Name of Company: Bopco, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, NM 88220	Telephone No.: (575) 887-7329
Facility Name: PLU 420 Tank Battery – Release 1	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner: Federal
API No.: 30-015-39795	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	25S	31E	700	South	1300	East	Eddy

Latitude: N 32° 5' 45.94" **Longitude:** W 103° 46' 42.24"**NATURE OF RELEASE**

Type of Release: Crude oil and produced water	Volume of Release: 5 bbl crude oil and 5 bbls produced water	Volume Recovered: 1 bbl crude oil
Source of Release: Heater-treater fire tube gasket	Date and Hour of Occurrence: 2/28/14 time unknown	Date and Hour of Discovery: 2/28/14 @ ~ 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
Depth to Water. ~310 ft bgs		
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* The gasket on the heater-treater fire tube failed. The production well was shut in and the gasket was replaced.		
Describe Area Affected and Cleanup Action Taken.* The spill affected approximately 3,200 sq. ft. of caliche well pad around the process equipment earthen containment and approximately 4,000 sq. ft. of pasture area was lightly misted. The process equipment and vegetation were washed down with soap and water the day of the release. All of the free standing fluid was picked up with a vacuum truck. The contaminated soil was excavated and hauled to a state approved facility for disposal and the excavation has been backfilled with clean soil. The spill area has been cleaned up in accordance to the NMOCD and BLM remediation guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Brad Blevins	Approved by District Supervisor:	
Title: EHS Asst. Remediation Foreman	Approval Date: 11/18/2014	Expiration Date: NA
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10-30-14 Phone: (432) 214-3704	FINAL	

* Attach Additional Sheets If Necessary

2RP-2250