

Received 11/18/2014

NMOCD Artesia

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

## OPERATOR

☐ Initial Report ☒ Final Report


<b>Name of Company:</b> Bopco, L.P.	<b>Contact:</b> Tony Savoie
<b>Address:</b> 522 W. Mermod, Suite 704 Carlsbad, NM 88220	<b>Telephone No.:</b> (575) 887-7329
<b>Facility Name:</b> PLU-57 Tank Battery	<b>Facility Type:</b> Exploration and Production
<b>Surface Owner:</b> Federal	<b>Mineral Owner:</b> Federal
<b>API No.:</b> 30-015-24269	

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	28	25S	31E					Eddy

**Latitude:** N 32.094735 **Longitude:** W 103.785760

## NATURE OF RELEASE

<b>Type of Release:</b> crude oil and produced water	<b>Volume of Release:</b> 3 bbls of crude oil and 15 bbls produced water	<b>Volume Recovered:</b> 2 bbls water
<b>Source of Release:</b> heater treater	<b>Date and Hour of Occurrence:</b> 6/7/13 time unknown	<b>Date and Hour of Discovery:</b> 6/7/13 @ 1:00 pm
<b>Was Immediate Notice Given?</b> <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	<b>If YES, To Whom?</b>	
<b>By Whom?</b>	<b>Date and Hour:</b>	
<b>Was a Watercourse Reached?</b> <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	<b>If YES, Volume Impacting the Watercourse:</b> Not Applicable	
<b>Depth to Water.</b> ~300 ft bgs		
<b>If a Watercourse was Impacted, Describe Fully.*</b> Not Applicable		
<b>Describe Cause of Problem and Remedial Action Taken.*</b> The gasket failed on the heater treater fire tube. The gasket was replaced.		
<b>Describe Area Affected and Cleanup Action Taken.*</b> Approximately 600 sq. ft. of tank battery pad was affected by the release. The free standing fluid was recovered. Contaminated soil has been excavated and hauled to a state approved disposal facility and the excavation has been backfilled with clean soil. The spill area has been remediated in accordance to the NMOCD and BLM guidelines.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
<b>Signature:</b> 	<b>OIL CONSERVATION DIVISION</b>	
<b>Printed Name:</b> Brad Blevins	<b>Approved by District Supervisor:</b>	
<b>Title:</b> EHS Asst. Remediation Foreman	<b>Approval Date:</b> 11/20/2014	<b>Expiration Date:</b> NA
<b>E-mail Address:</b> bblevins@basspet.com	<b>Conditions of Approval:</b> FINAL	<b>Attached</b> <input type="checkbox"/>
<b>Date:</b> 11-12-14 <b>Phone:</b> (432) 214-3704		

\* Attach Additional Sheets If Necessary

2RP-1730