

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 105 S. 4 <sup>TH</sup> Street		Telephone No. 575-748-1471
Facility Name Dolores AIL Federal #1	API Number 30-015-26547	Facility Type Battery
Surface Owner Federal	Mineral Owner Federal	Lease No. NM-65418

### LOCATION OF RELEASE

Unit Letter A	Section 14	Township 22S	Range 31E	Feet from the 660'	North/South Line North	Feet from the 430'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.39694 Longitude 103.74086

### NATURE OF RELEASE

Type of Release Produced Water; Crude Oil	Volume of Release 20 B/PW; 1 B/O	Volume Recovered 0 B/PW; 0 B/O
Source of Release Poly pipe on water line	Date and Hour of Occurrence 4/21/2013; PM	Date and Hour of Discovery 4/21/2013, PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? NA	
By Whom? NA	Date and Hour NA	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*

The poly pipe ruptured on main water line. All wells were turned off, tank valves were shut and personnel made sure there was no continuation of a spill. The water line was repaired.

Describe Area Affected and Cleanup Action Taken.\*

An approximate area of 36' X 100'. The release was around the tin horn to the east (across the lease road) of the Dolores battery. Some of the released water flowed across the lease road and onto the Dolores Battery production pad. All affected areas will have initial clean-up completed, and all excavated soils will be disposed of at an approved NMOCD facility. Vertical and horizontal delineation samples will be taken and sent to a NMOCD approved facility. **Depth to Ground Water: >100' (approximately 448', Section 16, T22S-R31E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Yates Petroleum requests closure, please see attached cover letter for additional information.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Amber Cannon</u>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Amber Cannon	Approved by District Supervisor:	Accepted for Record
Title: Environmental Regulatory Agent	Approval Date: 12/16/2014	Expiration Date: N/A
E-mail Address: acannon@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: Monday, October 28, 2013 Phone: 575-748-4111	2RP- <u>1635</u> Clean-up on Pad deferred until site closure.	

\* Attach Additional Sheets If Necessary

Site off pad (section 3) not fully delineated  
and will be monitored for chloride impact.