

Received 12/19/2014

NMOCD Artesia

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

## OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU-CVX-JV #027H. The spill is 1,470 ft. S.W. of the well pad	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42111
------------------------	------------------------	----------------------

## LOCATION OF RELEASE

Unit Letter E	Section 3	Township 25S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	--------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.160773° Longitude: W 103.770594°

## NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 15 bbls	Volume Recovered: 5 bbls
Source of Release: 10" lay flat frac hose	Date and Hour of Occurrence: 9/15/14 @ approx. 10:38 pm	Date and Hour of Discovery: 9/15/14 @ approx. 10:38 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD in person to Heather while in Artesia office	
By Whom? Tony Savoie	Date and Hour: 9/16/14 @ approx. 12:00 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.\* Not Applicable

Describe Cause of Problem and Remedial Action Taken.\*

A pickup truck operated by Baker Hughes backed over the frac hose creating a tear. The line was isolated and a section of hose was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The spill impacted approximately 1,800 sq. ft. of caliche lease road and bar-ditch. A vacuum truck on-site recovered the free standing fluid. The remainder of the spill soaked into the road. Samples were collected from the site and based on laboratory analytical results a notice of 'no further action required' was issued by the NMOCD for this site.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

## OIL CONSERVATION DIVISION

Signature: 

Printed Name: Bradley Blevins

Approved by Environmental Specialist:

Title: Assistant Remediation Foreman

Approval Date: 12/29/2014 Expiration Date: NA

E-mail Address: bblevins@basspet.com

Conditions of Approval:

FINAL

Attached ☐

Date: 12-15-14 Phone: 432-214-3704

\* Attach Additional Sheets If Necessary

2RP-2508