

From: [Lance Crenshaw](#)
To: [Bratcher, Mike, EMNRD](#)
Subject: RE: Closure report for Russell Turner Water Station
Date: Tuesday, March 31, 2015 10:45:13 AM

Mr. Bratcher,

We initially set sample points in the spill area, but we found out it was a lined facility, so we did not sample it. We just took out the contaminated soil down to the liner and replaced it with new pea gravel.

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]
Sent: Tuesday, March 31, 2015 10:24 AM
To: Lance Crenshaw
Subject: FW: Closure report for Russell Turner Water Station

Lance,

Do you guys have the analytical data that goes with this closure report? The site diagram shows sample points, but the data didn't make into the report.

Thanks,

Mike Bratcher
NMOCD District 2
811 S. First Street
Artesia, NM 88210
O: 575-748-1283 X108
C: 575-626-0857
F: 575-748-9720

From: Gonzales, EL [mailto:ELgonzales@linnenergy.com]
Sent: Thursday, March 05, 2015 9:08 AM
To: McCracken, Theresa
Subject: FW: Closure report for Russell Turner Water Station

FYI-----

From: Lance Crenshaw [mailto:lcrenshaw@diversifiedfsi.com]
Sent: Tuesday, March 03, 2015 3:24 PM
To: Gonzales, EL; Potter, Dennis; Michael Burton; Michael Patterson
Subject: Closure report for Russell Turner Water Station

Gentlemen,

Attached is the closure report for the Russell-Turner Water Station. If you have any questions, please feel free to reply to this email. Thank you for your time.

Lance Crenshaw
Project Manager
Diversified Environmental Services