

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 4/8/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: West Brushy 8 Federal SWD #1	Facility Type: SWD

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31675
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	8	26S	29E	660	North	330	East	Eddy

Latitude 32.0625249053514 Longitude -103.99867482237

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 900 bbls	Volume Recovered: 800 bbls
Source of Release: Water tank overflow	Date and Hour of Occurrence: 10/10/2014 7:30 am	Date and Hour of Discovery: 10/10/2014 7:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – OCD / James Amos – BLM	
By Whom? Amanda Trujillo	Date and Hour: 10/10/2014 5:46 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Human error. The battery was down for repair due to a pump failure with a well watcher on site to maintain well. Vacuum truck trucks were dispatched to remove all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

The majority of the impact was contained within the lined facility. Approximately 225'x100' was impacted outside the containment. All standing fluids were picked up and disposed of at an NMOCD approved facility. Souder, Miller and Associates addressed the clean-up of this location in accordance with NMOCD and BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 4/14/2015	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: April 6, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-2566