

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 4/27/2015

NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: West Brushy 5 Federal SWD #5	Facility Type: SWD

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-31869
------------------------	------------------------	----------------------

#### LOCATION OF RELEASE

Unit Letter P	Section 5	Township 26S	Range 29E	Feet from the 800	North/South Line South	Feet from the 850	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.0665385200141 Longitude -104.000346200798

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 225 bbls	Volume Recovered: 220 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 10-16-2014 7:30 pm	Date and Hour of Discovery: 10-16-2014 7:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – OCD / Jeffery Robertson – BLM	
By Whom? Amanda Trujillo	Date and Hour: 10/17/2014 4:40 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

An over pressured a poly flowline caused the release. Vacuum trucks were dispatched to pick up standing fluid and the flowline was repaired. All fluids were disposed of at an NMOCD approved facility.

Describe Area Affected and Cleanup Action Taken.\*

The impacted area was in the pasture approximately a half mile long and 2' wide. Concho had the spill site sampled to delineate any possible contamination from the release and presented a remediation work plan to the NMOCD and BLM for approval prior to any significant remediation work. All work has been performed in accordance to the approved work plan and stipulations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Lupe Carrasco		Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 4/29/2015	Expiration Date: N/A	
E-mail Address: gcarrasco@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: April 27, 2015	Phone: 575-748-6940	FINAL	

\* Attach Additional Sheets If Necessary

2RP-2586