

Received 4/28/2015

NMOCD Artesia

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S. First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Sterling Silver 33 Federal #1H	Facility Type	Well
Surface Owner	BLM	Mineral Owner	API No. 30-015-39831

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	33	23S	31E	360	South	590	East	Eddy County, NM

Latitude N 32.25453° Longitude W 103.77560°**NATURE OF RELEASE**

Type of Release	Oil	Volume of Release	120 bbls	Volume Recovered	100 bbls
Source of Release	Failure of head switch on a tank at the well	Date and Hour of Occurrence	09/18/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson- NMOCD, Sol Hughes- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	09/19/2014 @ 9:25 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The head switch on a tank at the well failed causing the tank to spill 120 bbls of oil onto the ground. The switch was reset and a vacuum truck recovered 100 bbls of oil.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 30' x 25' on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 01/27/2015 and approved by Sol Hughes of the BLM via email on 02/24/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Digitally signed by Chris Jones DN: cn=Chris Jones, o, ou, email=ckjones888@yahoo.com, c=US Date: 2015.04.21 12:53:14 -05'00'	OIL CONSERVATION DIVISION	
Signature: Chris Jones	Approved by Environmental Specialist:	
Printed Name: Christopher Jones	Approval Date: 5/4/2015	Expiration Date: NA
Title: HES Specialist	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
E-mail Address: Christopher.Jones@oxy.com		
Date:	Phone: (575) 628-4121	

* Attach Additional Sheets If Necessary

2RP-2545