

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 4/28/2015

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Edsels Wand Waver Fee #1	Facility Type: Battery

Surface Owner: Fee	Mineral Owner: Fee	API No. 30-015-32818
--------------------	--------------------	----------------------

LOCATION OF RELEASE

Unit Letter E	Section 6	Township 24S	Range 28E	Feet from the 1650'	North/South Line North	Feet from the 660'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.2497891677047 Longitude -104.133426949615

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 80 bbls Oil; 120 bbls PW	Volume Recovered: 78 bbls Oil; 118 bbls PW
Source of Release: Transfer pump failure	Date and Hour of Occurrence: 11/22/2014 9:50 am	Date and Hour of Discovery: 11/22/2014 9:50 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 11/26/2014 7:42pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A transfer pump failed, which caused the tanks to run over. Vacuum trucks were dispatched recover any standing fluid and dispose of at an NMOCD approved facility. Repairs were made to the failed equipment.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was contained to inside the bermed area. This is an unlined facility. Concho will had the spill site sampled to delineate any possible contamination from the release and presented a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Lupe Carrasco		Approved by Environmental Specialist:	
Title: Environmental Coordinator	Approval Date: 5/4/2015	Expiration Date: NA	
E-mail Address: gcarrasco@concho.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: April 28, 2015	Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-2643