

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/22/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Big Eddy Unit DI-9 #35H	Facility Type: Exploration and Production

Surface Owner: State	Mineral Owner: State	API No. 30-015-42007
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 21	Township 21S	Range 30E	Feet from the 90	North/South Line South	Feet from the 809	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	---------------------	---------------------------	----------------------	------------------------	----------------

Latitude N 32.45780 Longitude W 103.88015

NATURE OF RELEASE

Type of Release: Crude oil and Produced water	Volume of Release: 2 bbls crude oil and 7 bbls produced water	Volume Recovered: None
Source of Release: Frac tank and a pipe fitting.	Date and Hour of Occurrence: 7/18/14 about 5:00 a.m.	Date and Hour of Discovery: 7/18/14 at 6:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A hammer union leaked and the well had a gas kick overflowing the frac tank. The union was re-tightened

Describe Area Affected and Cleanup Action Taken.*

The spill impacted approximately 305 sq.ft. of caliche pad area around the frac tanks and approximately 1,585 sq.ft. of pasture area east of the well pad. All of the fluid soaked into the ground. The spill area was left as is. The impacted soil will be cleaned up in accordance to the NMOCD guidelines.
Basin Environmental began the remediation activities on 1/23/15 and completed the field work on 2/26/15, please find the attached Soil Closure Request Dated April 2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie		Approved by Environmental Specialist:	
Title: Waste Management and Remediation Specialist		Approval Date: 5/28/2015	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com		Conditions of Approval:	
Date: 5/22/15 Phone: 432-556-8730		FINAL Attached <input checked="" type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-2417