

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/22/2015

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: PLU-JV-CVX-BS #017H; 2RP #2781	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-40447

LOCATION OF RELEASE

Unit Letter C	Section 7	Township 25S	Range 31E	Feet from the 150	North/South Line North	Feet from the 1980	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.151692° Longitude: W 103.819416°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 320 bbls crude oil and 82 bbls PW	Volume Recovered: 315 bbls crude oil and 78 bbls PW
Source of Release: two phase separator	Date and Hour of Occurrence: 2/1/15 @ unknown	Date and Hour of Discovery: 2/1/15 @ approx. 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher, H. Patterson and Jim Amos BLM	
By Whom? Tony Savoie	Date and Hour: 2/2/15 @ 1:45 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* A sight glass failed on the two phase separator, the sight glass was replaced.		
Describe Area Affected and Cleanup Action Taken.* The majority of the spill was contained in 0-Perm containment around the process equipment. Due to the pressure of the release approximately 7,225 sq. ft. of caliche pad area was impacted by the release. A vacuum truck recovered 312 bbls of oil and 78 bbls of water from the containment, and picked up 3 bbls of oil off the ground. The equipment was power washed. It was estimated that a total of 5 bbls oil and 4 bbls of water saturated into the soil. The release area was remediated in conjunction with two other releases; 2RP-2613 and 2RP-2630. A portion of contaminated soil was excavated and hauled to a state approved disposal facility with remaining contaminated soil remediated on site. Based on laboratory analytical data and NMOCD approval the excavation has been backfilled with remediated soil. The area has been remediated in accordance to the NMOCD and BLM guidelines for spill remediation.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Bradley Blevins		Approved by Environmental Specialist:
Title: Assistant Remediation Foreman	Approval Date: 5/28/2015	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4-22-15	Phone: 432-214-3704	FINAL

* Attach Additional Sheets If Necessary

2RP-2781