

Received 6/26/2015

NMOCD Artesia

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.


**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr., Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Lost Tank 3 Federal #15	Facility Type	Well
Surface Owner	Oxy	Mineral Owner	
		API No.	30-015-37951

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	3	22S	31E	2558	North	235	West	Eddy County, NM

Latitude N 32.42078° Longitude W 103.77349°**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	6 bbls oil, 6 bbls produced water	Volume Recovered	0 bbls
Source of Release	Livestocked tampered and opened the 1" bleed valve on the well head	Date and Hour of Occurrence	09/15/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Heather Patterson- NMOCD, Sol Hughes- BLM			
By Whom?	Kathy Purvis, BBC International	Date and Hour	09/16/2014 @ 4:45 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Livestock tampered with and opened the 1" bleed valve on the well head spilling 6 bbls of oil and 6 bbls of produced water on to the ground. The valve was closed and a plug was installed.					
Describe Area Affected and Cleanup Action Taken.*					
The affected area is approximately 40' x 100' on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 11/03/2014 and approved by Sol Hughes of the BLM via email on 10/30/2014.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Chris Jones Digitally signed by Chris Jones DN: cn=Chris Jones, o=oxy, email=ckjones888@yahoo.com, c=US Date: 2015.05.12 09:45:53 -0500		<b>OIL CONSERVATION DIVISION</b>			
Signature: Jones		Approved by Environmental Specialist: 			
Printed Name: Christopher Jones					
Title: HES Specialist		Approval Date: 6/26/2015		Expiration Date: N/A	
E-mail Address: Christopher.Jones@oxy.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date:		Phone: (575) 628-4121		FINAL	

\* Attach Additional Sheets If Necessary

2RP-2544