

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 6/24/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Christopher Jones
Address	1502 W. Commerce Dr.; Carlsbad, NM	Telephone No.	(575) 628-4121
Facility Name	Lost Tank 3 Federal #21	Facility Type	well
Surface Owner	Mineral Owner	API No.	30-015-37920

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
E	3	22S	31E					Eddy County, NM

Latitude N 32.42078° Longitude W 103.77330°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	5 bbls oil, 5 bbls produced water	Volume Recovered	0 bbls
Source of Release	Excess pressure caused the stuffing box packing on the wellhead to blow out	Date and Hour of Occurrence	11/04/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD, Sol Hughes- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	11/05/2014 @ 3:29 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Excess pressure caused the stuffing box packing on the wellhead to blow out 5 bbls of oil and 5 bbls of produced water onto the ground. No fluids were recovered and the stuffing box packing was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 30' x 60' on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 04/09/2014 and approved by Sol Hughes of the BLM via email on 04/13/2014.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Chris Jones Signature: Printed Name: Christopher Jones Title: HES Specialist E-mail Address: Christopher.Jones@oxy.com Date: 5/20/15 Phone: (575) 628-4121	Digitally signed by Chris Jones DN: cn=Chris Jones, o=ou, email=ckjones88@yahoo.com , c=US Date: 2015.05.15 10:43:38 -05'00'	OIL CONSERVATION DIVISION Approved by Environmental Specialist:  Approval Date: 6/26/2015 Expiration Date: N/A Conditions of Approval: FINAL Attached <input type="checkbox"/>
---	---	---

* Attach Additional Sheets If Necessary

2RP-2604