

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1510331239

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: BOPCO, L.P.	Contact: Bradley Blevins	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329	
Facility Name: PLU #105; 2RP# 2942	Facility Type: Exploration and Production	
Surface Owner: State of New Mexico	Mineral Owner: State of New Mexico	API No. 30-015-27895

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	36	24S	30E	660	North	1980	East	Eddy

Latitude: N 32.179780° Longitude: W 103.832049°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 4 bbls crude oil, 3 bbls produced water	Volume Recovered: 1 bbl oil, 2 bbls produced water
Source of Release: 1/4" high pressure hose	Date and Hour of Occurrence: 4/8/15 @ unknown	Date and Hour of Discovery: 4/8/15 @ approx. 2:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	
If a Watercourse was Impacted, Describe Fully.* Not Applicable		
Describe Cause of Problem and Remedial Action Taken.* A 1/4" high pressure hose going from the wellhead to a high pressure shutdown switch failed. A valve was shut to isolate the line. The hose will be replaced with stainless steel tubing.		
Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 2,138 sq. ft. of caliche well pad. All of the free standing fluid was recovered with a vacuum truck. An EPI crew responded to the spill location on 4/9/15, all of the saturated soil was scraped up and placed on plastic pending the final remediation. Samples were collected, and based on laboratory analytical data and NMOCD approval the contaminated soil has been hauled to a state approved disposal facility, and the excavation backfilled with clean soil.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 9/2/15	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 8-24-15 Phone: 432-214-3704	FINAL	

* Attach Additional Sheets If Necessary

2RP-2942