

**From:** [Pam Inskeep](#)  
**To:** [Patterson, Heather, EMNRD](#)  
**Cc:** [Bratcher, Mike, EMNRD](#)  
**Subject:** FOLLOW UP: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325 OCD tracking number 2RP-3200  
**Date:** Monday, September 14, 2015 9:17:55 AM  
**Attachments:** 8808 JV-P Pardue D #1 sample analyses 09 10 2015.pdf

---

Good morning.

Attached, please find copies of the sample analyses performed at this site on 9/10/2015.

Please review and advise as to approval for excavation and backfill.

Thanks,

Pam

---

**From:** Patterson, Heather, EMNRD [mailto:Heather.Patterson@state.nm.us]  
**Sent:** Friday, August 21, 2015 10:17 AM  
**To:** Pam Inskeep <Pinskeep@btaoil.com>  
**Cc:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>  
**Subject:** RE: C141 - BTA 8808 JV-P Pardue D #1 30-015-26325

**BTA \* Pardue D 8808 JV-P #1 \* 30-015-26274 \* 2RP-3200**

Ms. Inskeep,

The OCD has received and processed your initial release notification for the above listed site. In the C-141 it is stated that BTA will excavate the contaminated soil and replace with clean soil. The OCD will require a full delineation at this site to be submitted in a work plan to the district 2 office before this site is excavated and backfilled. The OCD tracking number for this incident is 2RP-3200.

If you have any questions or concerns, please don't hesitate to call.

Thank you,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Pam Inskeep [mailto:Pinskeep@btaoil.com]  
**Sent:** Thursday, August 13, 2015 4:13 PM  
**To:** Patterson, Heather, EMNRD  
**Subject:** C141 - BTA 8808 JV-P Pardue D #1 30-015-26325

Good afternoon, Heather.

Attached is a C-141 initial report re our 8808 JV-P Pardue D #1.

Please give a shout with any questions.

Thanks,

Pam

Pam Inskeep  
Regulatory Administrator  
BTA Oil Producers LLC  
104 S. Pecos  
Midland, TX 79701  
432-682-3753  
[pinskeep@btaoil.com](mailto:pinskeep@btaoil.com)