

Bratcher, Mike, EMNRD

From: Fred Holmes <fred@etechemv.com>
Sent: Tuesday, February 28, 2012 3:30 PM
To: Bratcher, Mike, EMNRD; 'Gregston, Terry G'
Cc: 'Ron Ragland'; 'Joe Hernandez'; 'Stephen McGhee'
Subject: LINN Energy - Skelly B South Tank Battery Backfill Request
Attachments: Skelly B South Tank Battery Clearance Data.pdf

Dear Mike & Terry:

1. Attached is the analytical summary map and analytical data for the clearance sampling of the Skelly B South #274 Tank Battery.
2. Grab samples were collected from each corresponding sampling site and depth then placed in certified clean jars, labeled, and custody seals applied. Nitrile gloves were used and changed during each sample collection.
3. Samples were preserved according to the requirements ASATM/EPA requirements. Normal Chain of Custody procedures were observed.
4. LINN is requesting permission to backfill and close the site in accordance with the stipulations for the site.

Thank you for your assistance.

Fred Holmes

Etech Environmental & Safety Solutions, Inc.

P.O. Box 8469

Midland, Texas 79708-8469

Phone: 432-563-2200

Fax: 432-563-2213

E-mail: fred@etechemv.com

CONFIDENTIAL

This e-mail message, including any attachments, is intended solely for the individual(s) named above. It contains confidential and/or proprietary information. If you are not the intended recipient, please do not read, copy or distribute it or any information it contains. Please immediately notify the sender by return mail and delete it.