

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 11/11/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas	
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905	
Facility Name: Tamano 11 NC Fed #1H	Facility Type: Producing Oil Well	
Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-41350

LOCATION OF RELEASE

Unit Letter N	Section 11	Township 18S	Range 31E	Feet from the 150'	North/South Line South	Feet from the 2310'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.7552376 Longitude -103.84127

NATURE OF RELEASE

Type of Release: Oil/produced water	Volume of Release: estimated 20 bbls total fluid	Volume Recovered: 15 bbl Oil
Source of Release: Stuffing Box/ Well head	Date and Hour of Occurrence 9-25-15	Date and Hour of Discovery 9-25-15 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Stuffing Box blowout. Pumping unit was shut off and packing was replaced. DFSI environmental sampled four points of the leak area and a work plan was submitted and approved.

Describe Area Affected and Cleanup Action Taken.*

The well pad surface was affected as well as an approximate 60' X 45' area Southwest of pad where earth berm was washed out by heavy rainfall. A vacuum truck was used to recover 15 bbls of oil. DFSI personnel dug out pad area to 6" BGS and backfilled with fresh caliche. The pasture area was dug out to 1' BGS, backfilled with native topsoil, and re-seeded. For remediation details reference closure report dated November 11, 2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Zack Thomas	Approved by Environmental Specialist:		
Title: Environmental Rep.	Approval Date: 11/16/2015	Expiration Date: N/A	
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: 11-11-15	Phone: 575-602-2188		

* Attach Additional Sheets If Necessary

2RP-3303