

**From:** Patterson, Heather, EMNRD  
**To:** ["taylor16@aol.com"](mailto:taylor16@aol.com)  
**Cc:** [Bratcher, Mike, EMNRD](#); [Cordero, Gilbert, EMNRD](#)  
**Subject:** FW: Smith & Marrs  
**Date:** Thursday, November 12, 2015 12:36:00 PM

---

Ms. Taylor,

Please review the attached pictures. Our field inspector discovered a release on Monday at the Signal State #2. As he stated, the oil may be coming from below ground at this site.

The OCD will require a C-141 be turned in for this release as soon as possible. This is to be followed by a remediation plan submitted for OCD approval. Please contact me if you have any questions.

Thank you,

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

**From:** Cordero, Gilbert, EMNRD  
**Sent:** Monday, November 09, 2015 1:26 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Dade, Randy, EMNRD  
**Subject:** Smith & Marrs

Pics of standing oil around the well head. Appears to be coming from below ground level.  
Signal State #002 30-015-01901-00-00

*Sent from my Verizon Wireless 4G LTE DROID*