

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nMLB1413536397

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Pyote Water Solutions, LLC	Contact	Jerry Burton NM Operations Manager
Address	400 W Illinois, Ste 950	Telephone No.	(432)448-4917
Facility Name	Willow Lake SWD	Facility Type	Salt Water Disposal

Surface Owner	Pyote Water Solutions, LLC	Mineral Owner	Pyote Water Solutions, LLC	API No.	30-015-21499
---------------	----------------------------	---------------	----------------------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
				200 ft	South	no	no	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	production water	Volume of Release	1200 bbls	Volume Recovered	1200 bbls
Source of Release	Franco's driver hit cement barrier, took out load lines 1 & 2	Date and Hour of Occurrence	4-25-14	Date and Hour of Discovery	4/25/14 14:25 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jerry Burton NM Operations Manager		
By Whom?	anonymous driver reported this	Date and Hour	4/25/14 15:75 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
NONE

Describe Cause of Problem and Remedial Action Taken.*
see initial report

Describe Area Affected and Cleanup Action Taken.* 1. called in Talon for soil samples, checked high on chloride's. 2. Brought in S&B Services, LLC excavating, took out contaminated soil. (3) Talon came back in ran soil samples, chloride check was good. (4) S&B brought in fresh top soil. (5) Talon came back in and re-seeded with #2 BLM seed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Jerry Burton</i>		OIL CONSERVATION DIVISION	
Printed Name: Jerry Burton		Approved by Environmental Specialist: <i>MBratcher</i>	
Title: New Mexico Operations Manager		Approval Date: 1/7/2016	Expiration Date: N/A
E-mail Address: jerry@pyotewatersystems.com		Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 8-10-14 Phone: 432-448-4917		Final Report	

* Attach Additional Sheets If Necessary

2RP-2305