

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 2/26/2016  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report


Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Conoco 10 State #1	Facility Type	Well
Surface Owner	Private	Mineral Owner	API No. 30-015-23066

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	10	19S	29E	1980'	South	660'	East	Eddy County, NM

Latitude N 32.67332° Longitude W 104.05632°

### NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	10 bbls produced water, 2 bbls oil	Volume Recovered	Unknown
Source of Release	Gauge malfunctioned at well head	Date and Hour of Occurrence	04/15/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The gauge at the wellhead malfunctioned causing a release of mix fluids surrounding the wellhead. A vac truck was immediately called to the location and recovered unknown barrels of fluids.					
Describe Area Affected and Cleanup Action Taken.*					
The impacted area surrounding the wellhead and pump jack measures approximately 14' x 20'. All fluids stayed on location. Talon/LPE has already performed site assessment and soil sampling activities. Remediation was completed in accordance with the remediation plan approved by Heather Patterson of NMOCD via email on 05/06/2015.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		<u>OIL CONSERVATION DIVISION</u>			
Printed Name: Casey Summers		Approved by Environmental Specialist:			
Title: NM Environmental Advisor		Approval Date: 3/1/2016		Expiration Date: N/A	
E-mail Address: Casey_Summers@oxy.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 2-23-16 Phone: (575) 513-8289		FINAL			

\* Attach Additional Sheets If Necessary

2RP-2976