

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	State 2 #3 CTB	Facility Type	Battery
Surface Owner	State	Mineral Owner	API No. 30-015-26877

**LOCATION OF RELEASE**


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	2	22S	31E	2310'	South	330'	East	Eddy County, NM

Latitude N 32.41591° Longitude W 103.74235°

**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	90 bbls	Volume Recovered	85 bbls
Source of Release	2" Dump line corroded	Date and Hour of Occurrence	03/30/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?		Date and Hour			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
A 2" dump line corroded causing a 90 barrel release within the containment of the facility. A vac truck was immediately called to the location and recovered 85 barrels of fluid.					
Describe Area Affected and Cleanup Action Taken.*					
The impacted area was inside the containment of the facility. Talon/LPE has already performed site assessment and soil sampling activities. Remediation was completed in accordance with remediation plan approved by Heather Patterson of NMOCD via email on 05/06/2015.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					

**OIL CONSERVATION DIVISION**

Signature: 	Approved by Environmental Specialist: <b>Accepted for Record 3/2/2016</b> HMP	
Printed Name: Casey Summers	Approval Date: <u>N/A</u>	Expiration Date:
Title: NM Environmental Advisor	Conditions of Approval:	
E-mail Address: <u>Casey_Summers@oxy.com</u>	Contamination left in place due to	Attached <input type="checkbox"/>
Date: <u>2-23-16</u> Phone: (575) 513-8289		

\* Attach Additional Sheets If Necessary

equipment. Cleanup to be  
deferred until site abandonment

2RP-2975