

Received 3/21/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU #411H; 2RP #3107	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner:	API No. 30-015-39930
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 28	Township 24S	Range 31E	Feet from the 1000	North/South Line North	Feet from the 1850	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: N 32.192796° Longitude: W 103.780195°**NATURE OF RELEASE**

Type of Release: produced water/crude oil	Volume of Release: 3 bbls oil and 11 bbls PW	Volume Recovered: 1 bbls oil and 0 bbls PW
Source of Release: failed sight glass	Date and Hour of Occurrence: 7/2/15 @ 6:00 pm	Date and Hour of Discovery: 7/2/15 @ 6:28 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.* Not Applicable


Describe Cause of Problem and Remedial Action Taken.*

Release of oil and produced water occurred at the FWKO due to a failed sight glass. Affected well pad around production equipment, all fluid was contained within earth berm.

Describe Area Affected and Cleanup Action Taken.*

A vacuum truck was called to the location and was able to recover 1 barrel of oil. Contaminated soil was excavated and hauled to a state approved disposal facility and samples were collected. Based on laboratory analytical data and NMOCD approval the excavation has been backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist:	
Title: Assistant Remediation Foreman	Approval Date: 3/22/2016	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 3-18-16 Phone: 432-214-3704		

* Attach Additional Sheets If Necessary

2RP-3107