

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

fAB1519434694

Release Notification and Corrective Action

nAB1519434927

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Vanguard	Contact: JT Terry
Address: 4001 Penbrook, Suite 201, Odessa, Texas 79762	Telephone No. 432-362-2209
Facility Name: Water Disposal Line	Facility Type: polyline

Surface Owner: Federal	Mineral Owner: Federal	API No.
------------------------	------------------------	---------

LOCATION OF RELEASE

Unit Letter P	Section 12	Township 20S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude: N 32.581612° Longitude: W 104.021801°

NATURE OF RELEASE

Type of Release: produced water	Volume of Release: 10 bbls	Volume Recovered: 5 bbls
Source of Release: disposal line	Date and Hour of Occurrence: unknown	Date and Hour of Discovery: unknown
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	


If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*

The poly disposal line failed due to vehicle traffic. The line was repaired and moved.

Describe Area Affected and Cleanup Action Taken.* The spill impacted approximately 18,500 sq. ft. of lease road. A vacuum truck was brought in and picked up approximately 5 bbls of water. The area will be remediated in accordance to the NMOCD and BLM guidelines for spill remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: JT Terry		Approved by Environmental Specialist: <i>MBratcher</i>	
Title: Production Foreman		Approval Date: 4/13/2016	Expiration Date: N/A
E-mail Address: jterry@vnrlc.com		Conditions of Approval: N/A	
Date: _____ Phone: 432-362-2209		Attached <input type="checkbox"/>	
		FINAL	

* Attach Additional Sheets If Necessary

2RP-3098