

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/25/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: PURDY 8 FEDERAL #001	Facility Type: 30-015-36273

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-36273
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 08	Township 23S	Range 26E	Feet from the 1140'	North/South Line North	Feet from the 1240'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.3231697 Longitude -104.3110809

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 20 bbls Oil	Volume Recovered: 15 bbls oil
Source of Release: Tank	Date and Hour of Occurrence: 3/28/2016 8:00 am	Date and Hour of Discovery: 3/28/2016 8:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a hole in the tank. Vacuum trucks were dispatched to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined containment. Repairs were made to equipment, the containment was cleaned and the facility put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

<u>OIL CONSERVATION DIVISION</u>	
Signature: 	Approved by Environmental Specialist:
Printed Name: Amanda Trujillo Davis	
Title: Senior Environmental Coordinator	Approval Date: 5/31/2016 Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval:
Date: May 19, 2016 Phone: 575-748-6940	FINAL
	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3642