

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1615537888

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	EOG Resources, Inc. 7377	Contact	Zane Kurtz
Address	5509 Champions Drive, Midland, TX 79706	Telephone No.	432-425-2023
Facility Name	Cedar Lake 35 Fed Com 2	Facility Type	Oil and Gas Well
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-27851

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	35	17S	30E	990'	S	990'	E	Eddy

Latitude 32.7866 Longitude -103.9370

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	188bbls	Volume Recovered	2bbls
Source of Release	Oil tank bottom rotted out	Date and Hour of Occurrence	5-30-2016	Date and Hour of Discovery	1500
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NA			
By Whom? NA	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			


If a Watercourse was Impacted, Describe Fully.*
NA

Describe Cause of Problem and Remedial Action Taken.*

A hole developed in the bottom of an oil tank inside containment. Release was contained inside the dirt containment. Some leached through the berm walls onto the pad area. Nothing off pad. Consultant will delineate the vertical and horizontal depths of the release and submit a work plan for cleanup. Cleanup method will be based on test results to see if land farm or dig and haul is necessary.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zane Kurtz	Approved by Environmental Specialist:	
Title: Sr. Environmental Rep., EOG Resources, Inc.	Approval Date: 6/3/2016	Expiration Date: N/A
E-mail Address: zane_kurtz@eogresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6-1-2016 Phone: 432-425-2023	Remediation per OCD Rules and Guidelines	

* Attach Additional Sheets If Necessary

Submit Remediation Proposal No Later
Than 7/3/2016

2RP-3715