

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-685-4304
Facility Name: Tex Mack #202	Facility Type: Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-35914
----------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter N	Section 2	Township 17S	Range 31E	Feet from the 990'	North/South Line South	Feet from the 1650'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.8590803868665 Longitude -103.843618143308

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 25 bbls Oil	Volume Recovered: 20 bbls Oil
Source of Release: Heater Treater	Date and Hour of Occurrence: 2/7/2015 9:00 am	Date and Hour of Discovery: 2/7/2015 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

1/4" nipple on oil leg corroded and caused leak. Vacuum trucks were dispatched to recover all standing fluid and micro blaze was applied to the pasture.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the facility but an over spray in pasture occurred. Concho excavated the area of AH-1 down to 1' and scraped the area of AH-3. A confirmation sample for BTEX was collected in the bottom of AH-1 as requested by the NMOCD. The excavation was backfilled with fresh material and all contaminated material was hauled off to an approved disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 6/21/2016	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 06-14-2016 Phone: 432-685-4304	FINAL	

* Attach Additional Sheets If Necessary

2RP-2840