

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 6/29/2016

NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Winston Gas Com Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-28633

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	31	21S	24E					Eddy County, NM

Latitude N 32.44035° Longitude W 104.53667°

#### NATURE OF RELEASE

Type of Release	Oil	Volume of Release	12 bbls	Volume Recovered	10 bbls
Source of Release	Blow out of the manway gasket on the heater treater	Date and Hour of Occurrence	06/19/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD, Shelly Tucker- BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	06/20/2016 @ 3:12 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

A blow out of the manway gasket on the heater treater caused 12 bbls of oil to leak into the lined containment. A vacuum truck recovered 10 bbls of oil and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 18' x 18' on location inside the lined containment. Remediation will be completed by removing the affected material and replacing it with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Casey Summers			Approved by Environmental Specialist:	
Title:	NM Environmental Advisor			Approval Date:	7/8/2016
E-mail Address:	Casey.Summers@oxy.com			Expiration Date:	N/A
Date:	6-29-16			Conditions of Approval:	N/A
Phone:	(575) 513-8289			Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

2RP-3770