

Received 7/20/2016

NMOCD Artesia

District I

1625 N. French Dr., Hobbs, NM 88240

District II

811 S First St., Artesia, NM 88210

District III

1000 Rio Brazos Road, Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Sarah State Com #1 O Battery	Facility Type	Gathering
Surface Owner	State	Mineral Owner	API No. 30-015-34693

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	10	19S	29E					Eddy

Latitude N 32.66947° Longitude W 104.06097°**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	70 bbls	Volume Recovered	0 bbls
Source of Release	Load line struck by backhoe	Date and Hour of Occurrence	12/31/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- NMOCD		
By Whom?	Cliff Brunson @ BBC International Inc.	Date and Hour	01/04/2016 in the afternoon		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A backhoe struck a load line while clearing snow causing 70 bbls of produced water to leak onto the ground. No fluids were recovered and the line was repaired/replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 35' x 30' on location inside the berm. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 03/17/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:

Printed Name: Casey Summers

Title: NM Environmental Advisor

E-mail Address: Casey\_Summers@oxy.comDate: 7-14-16

Phone: (575) 513-8289

Approved by Environmental Specialist:

Approval Date: 7/21/2016

Expiration Date: N/A

Conditions of Approval:

FINAL

Attached ☐

\* Attach Additional Sheets If Necessary

2RP-3485