

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/8/2016

NMOCD Artesia

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	SM Energy Company	Contact	Vickie Martinez
Address	3300 N "A" ST BLDG 7-200 Midland, TX 79705	Telephone No.	(432) 688-1709
Facility Name	EDSU #6 30-015-25385	Facility Type	Well

Surface Owner: BLM	Mineral Owner: BLM	Lease No. (API#) NMNM101361X
--------------------	--------------------	------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	24	18S	31E	890	North	990	East	Eddy

Latitude N 32.73581° Longitude W 103.81964°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release 20 bbls	Volume Recovered 15 bbls
Source of Release: 3" Polyethylene Flowline	Date and Hour of Occurrence 8/12/2012 6:00 A.M.	Date and Hour of Discovery 8/12/2012 6:00 A.M.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos - BLM	
By Whom? Bill Hearne	Date and Hour 8/12/2012 2:53 P.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

3" Polyethylene flowline leak in butt weld. Cut off bad section of line, re-dressed ends and welded pipe back together.

Describe Area Affected and Cleanup Action Taken.*

Tetra Tech personnel inspected the site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature:

Printed Name: Aaron Hale

Title: Project Manager

E-mail Address: Aaron.Hale@TetraTech.com

Date:

Phone: (432) 682-4559

Approved by District Supervisor:

Approval Date: 8/9/2016

Expiration Date: N/A

Conditions of Approval:

FINAL

Attached ☐

* Attach Additional Sheets If Necessary

2RP-1257