

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 8/8/2016  
NMOCD Artesia

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	SM Energy Company	Contact	Vickie Martinez
Address	3300 N "A" ST BLDG 7-200 Midland, TX 79705	Telephone No.	(432) 688-1709
Facility Name	PDU 208	Facility Type	Well
Surface Owner: BLM		Mineral Owner: BLM	Lease No. (API#) 30-015-34433

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	35	19S	29E	1438	North	969	East	Eddy

Latitude N 32.62035° Longitude W 104.04020°

#### NATURE OF RELEASE

Type of Release: Oil/Produced Water	Volume of Release 9 bbls	Volume Recovered 5 bbls
Source of Release: Stuffing Box	Date and Hour of Occurrence 4/25/2012	Date and Hour of Discovery same.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Jim Amos - BLM	
By Whom? Bill Hearne	Date and Hour 4/25/2012 10:16 A.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Wellbore was hot watered on 4/24/12 and pumping unit was left on hand instead of auto. Well pumped off burning stuffing box packing causing box to leak. SM energy company will turn this over to Tetra Tech for further evaluation.

Describe Area Affected and Cleanup Action Taken.\*

Tetra Tech personnel inspected the site and collected samples to define spills extent. Soil that exceeded RRAL was removed and hauled away for proper disposal. The site was then brought up to surface grade with clean backfill material. Tetra Tech prepared a closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Ike Tavarez, PG (Agent for SM Energy)		Approved by District Supervisor:	
Title: Project Manager		Approval Date: 8/9/2016	Expiration Date: N/A
E-mail Address: ike.tavarez@TetraTech.com		Conditions of Approval:	
Date: 2/25/13 Phone: (432) 682-4559		FINAL Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

2RP-1146