

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Devon Energy Production	Contact Mike McMahan Assistant Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No. 575.706.4165
Facility Name Grandi 22-3	Facility Type Gas

Surface Owner	Mineral Owner State	API No. 30-015-33922
---------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 22	Township 22S	Range 27E	Feet from the 660	North/South Line FNL	Feet from the 1210	East/West Line FEL	County EDDY
------------------	---------------	-----------------	--------------	----------------------	-------------------------	-----------------------	-----------------------	----------------


NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release Unknown	Volume Recovered 0
Source of Release Produced water line to SWD was damaged by third party	Date and Hour of Occurrence 12/15/2016 @ 12:00 pm	Date and Hour of Discovery 3/18/2016 @ 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/ A		

Describe Cause of Problem and Remedial Action Taken.* On July 2, 2015 Blue Wally Construction submitted a OneCall ticket for installing a sprinkler system for a private home owner. Devon Energy's line locating department responded with a positive response by flagging the line and requesting in the notes that the construction company was to contact Devon so that a representative could be present at the time of the installation of the sprinklers. Blue Wally Construction failed to contact Devon Energy as requested and installed the sprinkler system. In March 2016, the home owner contacted Devon Energy believing that the line had developed a leak due to staining in his yard. Devon pressured the line on March 18, 2016 to identify exactly where the leak was located. On March 21, 2016 Devon excavated a small area around the line to identify how the line had failed. A cut into the Devon line was identified right underneath the sprinkler system line that was routed over the top of the Devon line. The coordinates are 32.383947, -104.168534

Describe Area Affected and Cleanup Action Taken.* Talon/LPE was contracted by Devon Energy for the correction of this release. Pursuant to our work plan approved by the BLM and NMOCD, The impacted areas within the yard were excavated down to the rock shelf utilizing a roustabout crew to expose the utility lines. A backhoe and roustabout crews were used to excavate the majority of the impacted area down to the rock shelf in the landowner's yard and around several utility lines. The dead trees were removed and a trench was excavated along the tree line approximately 75-feet long by 6-feet deep and 3-feet wide utilizing a hammer-hoe. A 2-foot clay liner was installed into the bottom of the excavation at the tree line and the entire excavated area was backfilled with new locally obtained top soil. The work area was contoured to match the surrounding landscape. No further action is required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Brett Fulks	Approved by Environmental Specialist:		
Title: EHS Professional	Approval Date: 8/29/2016	Expiration Date: N/A	
E-mail Address: brett.fulks@dmn.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 8/18/2016	Phone: 432-301-3223		FINAL

2RP-3647