

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV BS #006H AKA Big Sinks State #1H; 2RP#3625	Facility Type: Exploration and Production

Surface Owner: State	Mineral Owner: State	API No. 30-015-39246
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter E	Section 2	Township 24S	Range 30E	Feet from the 1980	North/South Line North	Feet from the 200	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude: N 32.248886° Longitude: W 103.859261°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 16 barrels	Volume Recovered: 10 barrels
Source of Release: corrosion to pipe threads	Date and Hour of Occurrence: 3/22/16 @ 2:00 pm	Date and Hour of Discovery: 3/22/16 @ 2:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*

Pipe threads failed due to corrosion causing line to leak. A vacuum truck was called to the location and recovered 10 barrels of produced water from the ground surface. A contract gang replaced the failed piping.

Describe Area Affected and Cleanup Action Taken.*

Produced water was released to the well pad and along the containment wall. Samples were collected, and based on laboratory analytical data and NMOCD approval: the contaminated soil was excavated and hauled to a state approved disposal facility and the excavation backfilled with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 

Printed Name: Bradley Blevins

Approved by Environmental Specialist:

Title: Assistant Remediation Foreman

Approval Date: 9/8/2016

Expiration Date: N/A

E-mail Address: bblevins@basspet.com

Conditions of Approval:

FINAL

Attached ☐

Date: 8-3-16 Phone: 432-214-3704

* Attach Additional Sheets If Necessary

2RP-3625