

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 9/12/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | |
|--|----------------------------|----------------------|
| Name of Company: Mewbourne Oil Company | Contact: Zack Thomas | |
| Address: PO Box 5270 Hobbs NM 88241 | Telephone No. 575-393-5905 | |
| Facility Name: Delaware Ranch SWD | Facility Type: Disposal | |
| Surface Owner: Private | Mineral Owner: N/A | API No. 30-015-22734 |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------------|-----------------|--------------|-----------------------|---------------------------|-----------------------|------------------------|----------------|
| Unit Letter | Section 11 | Township 26S | Range 28E | Feet from the 660' | North/South Line South | Feet from the 660' | East/West Line East | County Eddy |
|-------------|---------------|-----------------|--------------|-----------------------|---------------------------|-----------------------|------------------------|----------------|

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|--|---|--------------------------------------|
| Type of Release: Overflow | Volume of Release: 50 bbls | Volume Recovered: 0 bbls |
| Source of Release: Tank thief hatch | Date and Hour of Occurrence 7-3-13 | Date and Hour of Discovery 7-3-13 |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? George Brantley | |
| By Whom? Zack Thomas | Date and Hour 7-5-13 | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* SWD pump did not kick on automatically therefore tanks were ran over. When pumper arrived on location he immediately started swd pump which stopped the leak. | | |
| Describe Area Affected and Cleanup Action Taken.* Leak contaminated a 150 ft by 25 ft area west of the tank containment. All fluids stayed on the pad. Contaminated soil will be excavated and hauled to LeaLand. Samples from the pad were taken on November 24, 2014 in connection with 2RP-2534. | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: <i>Z. Thomas</i> | <u>OIL CONSERVATION DIVISION</u> | |
| Printed Name: Zack Thomas | Approved by Environmental Specialist: | |
| Title: Environmental Rep. | Approval Date: 9/19/2016 | Expiration Date: N/A |
| E-mail Address: zthomas@mewbourne.com | Conditions of Approval: FINAL | Attached <input type="checkbox"/> |
| Date: 9-12-16 | Phone: 575-602-2188 | |

* Attach Additional Sheets If Necessary

2RP-1723