

**From:** Patterson, Heather, EMNRD  
**To:** ["Zack Thomas"](#)  
**Cc:** [Bratcher, Mike, EMNRD](#)  
**Subject:** RE: Pine Box 17 AP Fed #1 2RP-2253  
**Date:** Monday, September 26, 2016 9:35:00 AM  
**Attachments:** image001.png  
image002.png

---

Zack,

We will need analytical results for this one, and a closure report. Do you know how deep the excavation went? If you could get samples at the excavation depth and just below to show it was fully cleaned up. Also, was the containment area lined? If not, we will need a delineation of that area.

Give me a call if you have any more questions.

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Zack Thomas [mailto:[zthomas@mewbourne.com](mailto:zthomas@mewbourne.com)]  
**Sent:** Thursday, September 22, 2016 9:48 AM  
**To:** Patterson, Heather, EMNRD  
**Cc:** Bratcher, Mike, EMNRD  
**Subject:** Pine Box 17 AP Fed #1 2RP-2253

Heather,

We hauled off all stained material from the pad surface as well as the reclaimed area (which was just overspray). However I can't find any sample data for this release. We have established good vegetation across the reclaimed area and the pad looks fairly good. I have attached some pictures of what the site looks like currently. Let me know what you think and what I should do for this. Thank you



**Zack Thomas**  
Environmental Rep.  
Mewbourne Oil Company  
[PO Box 5270](#)  
Hobbs, NM 88241 US

Phone: (575) 393-5905 | Fax: (575) 397-6252  
(575) 602-2188  
Email: [zthomas@mewbourne.com](mailto:zthomas@mewbourne.com)



**MEWBOURNE**  
**OIL COMPANY**