

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 10/5/2016  
NMOCD Dist 2

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nAB1606056506

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: LOUISE FEE #001	Facility Type: Wellhead	
Surface Owner: Fee	Mineral Owner: Fee	API No. 30-015-32988

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	10	22S	27E	990'	North	990'	West	Eddy

Latitude 32.4118195 Longitude -104.1830292

**NATURE OF RELEASE**

Type of Release: Oil & Produced Water	Volume of Release: 20 bbls Oil ; 40 bbls PW	Volume Recovered: 18 bbls Oil ; 27 bbls PW
Source of Release: Stuffing box leak	Date and Hour of Occurrence: 2/11/2016 10:15 am	Date and Hour of Discovery: 2/11/2016 10:15 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Robert Grubbs Jr.	Date and Hour: Friday, February 12, 2016 8:19 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

The release was caused by a well packing and a clogged back pressure regulator. A vacuum truck was dispatched to recover standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

This release remained on the pad area around the wellhead. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <i>MBratcher</i>		
Title: Senior Environmental Coordinator	Approval Date: 10/5/16	Expiration Date: N/A	
E-mail Address: rgrubbs@concho.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: October 05, 2016 Phone: 432-683-7443	FINAL		

\* Attach Additional Sheets If Necessary

Remedial work performed per approved  
remediation proposal.

2RP-3571