

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 10/20/2016

NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Devon Energy Production	Contact	Jake Harrington, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	432-214-5175
Facility Name	Cotton Draw Unit 65-lease road	Facility Type	Salt Water Disposal
Surface Owner	Federal	Mineral Owner	State
		API No.	30-015-10843

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	25S	31E	1980	North	1980	East	Eddy

Latitude: 32.161085918

Longitude: -103.746039442

### NATURE OF RELEASE

Type of Release Produced water	Volume of Release 2bbbls	Volume Recovered 0bbbls
Source of Release Flow line next to road	Date and Hour of Occurrence December 22, 2015 1:00 PM	Date and Hour of Discovery December 22, 2015 1:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, BLM Mike Bratcher, OCD	
By Whom? Ray Carter, Assistant Production Foreman	Date and Hour Jim Amos, BLM December 23, 2015 1:05 PM Mike Bratcher, OCD December 23, 2015 1:10 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

#### Describe Cause of Problem and Remedial Action Taken.\*

Flow line to the East of the lease road was struck by unknown object and cut causing a 2bbl spray in the lease road. The transfer pump was immediately isolated and a crew was contacted to fuse the line back together. Repairs have been made to the line.

#### Describe Area Affected and Cleanup Action Taken.\*

2bbbls of produced water was released from a flow line. The size of the affected area is 10'x10' contained completely on the lease road to the East of the Cotton Draw Unit 65. 0bbbls were recovered and an environmental agency will be contacted for remediation.

The hydrocarbon impacted soil within the flow path from S-1 through S-3 was excavated to a depth of 0.5-feet deep. The 2 barrel overspray on the lease road East of the location in regards to Incident number 2RP-3467 was also scraped 0.5-feet while excavating in the vicinity of S-3. The impacted area within the S-4 flow path was excavated to the depth of 1-foot deep. All contaminated soil was transported to Lea Land, LLC; an approved disposal facility. The excavated areas on location and lease road were backfilled with new caliche, machine compacted and re-contoured to match the surrounding location.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sheila Fisher</i>	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: <b>Sheila Fisher</b>	Approved by Environmental Specialist:		
Title: <b>Field Admin Support</b>	Approval Date: 10/21/2016	Expiration Date: N/A	
E-mail Address: <b>Sheila.Fisher@dmn.com</b>	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10/20/16	Phone: <b>575.748.1829</b>		FINAL

\* Attach Additional Sheets If Necessary

2RP-3467