

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 10/20/2016  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	SRO SWD #104	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:	API No.	30-015-25864
----------------	-------	----------------	---------	--------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	10	26S	28E	1980'	North	1980'	West	Eddy

Latitude 32.0588913 Longitude 104.0774612

#### NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	150bbls	Volume Recovered:	148bbls
Source of Release:	Header	Date and Hour of Occurrence:	09-04-2016 02:30 am	Date and Hour of Discovery:	09-04-2016 02:30 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD / Amber Groves - SLO		
By Whom?	Robert Grubbs Jr	Date and Hour:	Mon 9/5/2016 10:36 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

The weld failed holding the header together. Refused the header back together.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho had the free fluids and any contaminated material inside the lined facility removed. The liner has been cleaned and returned back to normal operations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist:	
Title:	Senior Environmental Coordinator	Approval Date:	10/21/2016
E-mail Address:	rgrubbs@concho.com	Expiration Date:	N/A
Date:	October 20, 2016	Phone:	432-683-7443
		Conditions of Approval:	Attached <input type="checkbox"/>
		FINAL	

\* Attach Additional Sheets If Necessary

2RP-3879