

**From:** [Sheldon Hitchcock](#)  
**To:** [Patterson, Heather, EMNRD](#); [Kimberly M. Wilson](#)  
**Cc:** [Bratcher, Mike, EMNRD](#); [Tucker, Shelly](#); ["Chris Morphew"](#); [jamest@daktoares.com](mailto:jamest@daktoares.com)  
**Subject:** RE: Dakota Resources Trigg Fed 1  
**Date:** Tuesday, October 11, 2016 3:03:01 PM  
**Attachments:** image002.png  
H602152R TALON.PDF  
H602283 TALON.PDF

---

Heather, Shelly,

The TPH and BTEX results for the sidewalls around S-4 are attached. As you will see the North sidewall was above RRAL's during our first sample event. We extended that sidewall to the north another few feet and it is now clean. At this time I would like permission to backfill the excavation.

Respectfully,

**Sheldon Hitchcock**

**Project Manager**

Office: 575.746.8768  
Direct: 575.616.4021  
Cell: 575.689.5198  
Fax: 575.746.8905  
Emergency: 866.742.0742  
Web: [www.talonlpe.com](http://www.talonlpe.com)



---

**From:** Patterson, Heather, EMNRD [<mailto:Heather.Patterson@state.nm.us>]  
**Sent:** Friday, September 16, 2016 9:30 AM  
**To:** Kimberly M. Wilson <[kwilson@talonlpe.com](mailto:kwilson@talonlpe.com)>  
**Cc:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Sheldon Hitchcock <[slhitchcock@talonlpe.com](mailto:slhitchcock@talonlpe.com)>; David Adkins <[dadkins@talonlpe.com](mailto:dadkins@talonlpe.com)>; Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Subject:** RE: Dakota Resources Trigg Fed 1

Kimberly,

Did you get the confirmation samples for S-4?

Heather Patterson  
Environmental Specialist  
NMOCD District II  
Office (575)748-1283 ext.101  
Cell (575)703-0228

---

**From:** Kimberly M. Wilson [<mailto:kwilson@talonlpe.com>]  
**Sent:** Thursday, September 15, 2016 1:55 PM

**To:** Patterson, Heather, EMNRD

**Cc:** Bratcher, Mike, EMNRD; Sheldon Hitchcock; David Adkins

**Subject:** Dakota Resources Trigg Fed 1

RE: Dakota Resources \* Trigg Fed 001 \* 30-015-25006 \* L-7-21s-28e \* Eddy County, New Mexico

NMOCD Tracking Number: **2RP-1814** \* Date of release: 8/16/2013

Heather,

Good afternoon. Attached is the site map for the above referenced location. Yesterday I pulled soil samples from the sidewalls (N, S, E) around sample location S-5. I performed field titration for chlorides on site. My results are as follows: North sidewall = 212 mg/kg, South sidewall = 567 mg/kg, East sidewall = 212 mg/kg

On behalf of our client, we would respectfully request permission to begin backfilling operations on this project.

If you have any questions or concerns please feel free to contact me. Thank you.

**Kimberly M. Wilson**

**Project Manager**

Office: 575.746.8768

Direct: 575.616.4023

Cell: 575.602.3826

Fax: 575.746.8905

Emergency: 866.742.0742

Web: [www.talonlpe.com](http://www.talonlpe.com)

