

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/17/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	Contact Robert Asher	
Address 104 S. 4 th Street	Telephone No. 575-748-1471	
Facility Name Antweil ANU Federal #4-H	Facility Type Battery	
Surface Owner Federal	Mineral Owner Federal	API No. 30-015-40426

LOCATION OF RELEASE

Unit Letter M	Section 29	Township 19S	Range 30E	Feet from the 860	North/South Line South	Feet from the 660	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.62641 Longitude 104.0001

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 30 B/O	Volume Recovered 29 B/O
Source of Release Heater Treater	Date and Hour of Occurrence 2/17/2015; AM	Date and Hour of Discovery 2/17/2015; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 2/18/2015; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The back pressure valve on the heater treater failed, causing the release. Vacuum truck(s) and roustabout crews were called.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 40' x 120' within the lined and bermed battery, and approximate area of 40' x 40' outside of the battery. The back pressure valve was replaced after a vacuum truck recovered most of the released crude oil (29 B/O). Impacted gravel will be hauled to a NMOCD approved facility. Vertical and horizontal delineation samples will be taken and analysis ran for TPH & BTEX. If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 10) a Final Report, C-141 will be submitted to the OCD requesting closure. **Depth to Ground Water: 50-99' (approximately 90', Section 29, T19S-R30E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 10. Based on attached remedial actions and analytical results, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Robert Asher	Approved by Environmental Specialist:		
Title: NM Environmental Regulatory Supervisor	Approval Date: 12/1/2016	Expiration Date: N/A	
E-mail Address: boba@yatespetroleum.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: October 17, 2016	Phone: 575-748-4217	2RP-2835	final

* Attach Additional Sheets If Necessary