



Location Sign August 10, 2017



Location Viewing South Prior to Excavation, April 12, 2017





Location Viewing North, June 2, 2017



Location Viewing East Prior to Remediation and Chloride Delineation at DP-11, August 10, 2017





Soil Excavation near DP-7 Viewing Southwest, August 10, 2017



Soil Excavation along South Side of Spill Area Viewing East, August 10, 2017





Soil Excavation at S-15 Viewing North, August 11, 2017



Excavation Area Viewing West, August 11, 17





Final Excavation Area Viewing West, August 16, 2017



Final Excavation Area Viewing South, August 16, 2017