

Received 6/9/2017

NMOCD Dist 2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1634937547

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	MYOX 32 FEE #002H	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:	API No.	30-015-41521
----------------	-------	----------------	---------	--------------

LOCATION OF RELEASE

Unit Letter C	Section 32	Township 25S	Range 28E	Feet from the 190'	North/South Line North	Feet from the 1980'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.0927238 Longitude 104.1114349

NATURE OF RELEASE

Type of Release:	Oil	Volume of Release:	143bbbls	Volume Recovered:	141bbbls
Source of Release:	Oil Tank	Date and Hour of Occurrence:	12-10-2016 09:00 am	Date and Hour of Discovery:	12-10-2016 09:00 am
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher - NMOCD / Amber Groves - SLO		
By Whom?	Robert Grubbs Jr	Date and Hour:	Mon 12/12/2016 10:55 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

The release was caused by a hole in the oil tank. The oil tank is being replaced with a new 500 bbl. tank.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho had the free fluids and any contaminated material inside the lined facility removed. The liner has been cleaned and returned back to normal operations.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist: 	
Title:	Senior HSE Coordinator	Approval Date: 9/14/17	Expiration Date: N/A
E-mail Address:	rgrubbs@concho.com	Conditions of Approval: N/A FINAL	Attached <input type="checkbox"/>
Date:	April 27, 2017	Phone:	432-683-7443

* Attach Additional Sheets If Necessary

2RP-4031