

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1617326472

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland, TX 79701	Telephone No. 432-230-0077
Facility Name: USP Fee #002H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner:	API No. 30-015-34438
----------------------	----------------	----------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	23S	29E	319	North	946	West	Eddy County, NM

Latitude N 32.31158° Longitude W 103.99517°

#### NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 17 bbls	Volume Recovered: 16 bbls
Source of Release: Heater Treater	Date and Hour of Occurrence 06/17/2016 @ 1:00 pm	Date and Hour of Discovery 06/17/2016 @ 1:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A fitting on the bottom of the heater treater failed due to corrosion; replaced the fitting with a new one.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within a lined facility. A vacuum truck was dispatched to remove all free-standing fluid. Remediation was completed by removing the contaminated materials from within the lined facility and replacing it with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Rebecca Haskell	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Senior HSE Coordinator	Approval Date: 9/29/17	Expiration Date: N/A
E-mail Address: rhaskell@concho.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: <i>May 11, 2017</i> Phone: (432) 683-7443	FINAL	

\* Attach Additional Sheets If Necessary

2RP-3747