

Bratcher, Mike, EMNRD

From: Michael Burton <mburton@diversifiedfsi.com>
Sent: Wednesday, May 31, 2017 10:59 AM
To: Bratcher, Mike, EMNRD; Tucker, Shelly
Cc: Laura Flores
Subject: Skelly 247 spill
Attachments: LINN SKELLY UNIT #247.xlsm; IMG_0216.JPG; IMG_0226.JPG; YUN00078.jpg

Mike/Shelly,

Before we write the work plan on this release I would like to know if you have a problem with us deferring the soil removal until the last well accessed by this road to be abandoned.

We sampled the spill at the header (release point) and several other locations in the road. The spill ran into the road and settled into a low area in the road before it was located. We scraped the road from 6" to 1' BGS then backfilled with clean caliche. Logistically digging up the road will put a hindrance on production. Thoughts?

Mike Burton

DFSI

Environmental Operations Director

Customer Relations

575-390-5454 cell

The information contained in this e-mail message is intended only for the personal and confidential use of the recipient(s) named above. If the reader of this message is not the intended recipient or an agent responsible for delivering it to the intended recipient, you are hereby notified that you have received this document in error and that any review, dissemination, distribution, or copying of this message is strictly prohibited. If you have received this communication in error, please notify us immediately by e-mail, and delete the original message.