

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1720539234

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC [229137]	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: BUENA VISTA 2 STATE #001H	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-40789
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	02	20S	30E	1130'	South	330'	East	Eddy

Latitude 32.5981522 Longitude -103.9353943

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 27 bbls PW	Volume Recovered: 25 bbls PW
Source of Release: Fittings/Connections	Date and Hour of Occurrence: 7-13-2017 7:45 AM	Date and Hour of Discovery: 7/13/2017 7:45 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Crystal Weaver/NMOCD, Amber Groves/SLO	
By Whom? Aaron Lieb	Date and Hour: 7-13-2017 3:37 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release occurred due to a loose connection on a 4 inch pw line. The connection was tightened.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the lined containment of the facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho has had the free fluids and any impacted material inside the lined facility removed. The liner has been cleaned and the facility is back in operation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dakota Neel	Approved by Environmental Specialist: 	
Title: HSE Coordinator	Approval Date: 10/11/17	Expiration Date: N/A
E-mail Address: dneel2@concho.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: September 19, 2017 Phone: 575-746-2010	FINAL	

* Attach Additional Sheets If Necessary.

2RP-4302