

DELINEATION/REMEDIACTION REQUIRED

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1706936784

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Maverick Operating, LLC	Contact	Emily Sirgo
Address	1004 N Big Spring Street, Suite 121, Midland, TX, 79701	Telephone No.	432-682-2500
Facility Name	Poker Lake Unit #36	Facility Type	Injection Battery
Surface Owner	Federal	Mineral Owner	Federal
		API No.	300151085900

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	24S	31E	660	South	660	East	Eddy

Latitude 32.182750 Longitude -103.775710

NATURE OF RELEASE

Type of Release	Salt Water	Volume of Release	40	Volume Recovered	32
Source of Release	Water Tank	Date and Hour of Occurrence		Date and Hour of Discovery	2/26/2017 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Operator and Mike Bratcher		
By Whom?		Date and Hour	2/26/2017 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


Head switch at disposal pump hung and pumped water tanks empty. Pump then became air locked/stuck and ran tanks over as a result. Called out vacuum truck upon notice of spill to clean up fluid and scraped dirty soil. R360 environmental solutions to haul dirty soil off.

Pump is fixed to where it is pumping fluid.

Describe Area Affected and Cleanup Action Taken.*

Area affected around tanks inside the firewall. Vacuumed up fluid, scraped dirty soil up and R360 to haul dirt. Made sure firewall was built up after cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:			
Printed Name:	Emily Sirgo	Approved by Environmental Specialist: NOT APPROVED	
Title:		Approval Date:	Expiration Date: AT THIS TIME
E-mail Address:	emily@mogc-kec.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date:	3/2/2017	Phone:	4326822500

* Attach Additional Sheets If Necessary

2RP-4136