

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Tuesday, January 3, 2017 8:46 AM
To: 'Blaney, Karolina'; Weaver, Crystal, EMNRD
Cc: stucker@blm.gov
Subject: RE: WPX Brushy Draw Booster Station - initial C-141

RE: WPX/RKI * Brushy Draw Booster Station * **2RP-4011** * DOR: 11/13/16

Karolina,

Your delineation proposal is approved. OCD will review the data generated using EM & ERT delineation methods, however be aware that OCD may require a traditional soil sample delineation at some point in the project.

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

If you have any questions or concerns, and for notification, please contact me.

Mike Bratcher
NMOCD District 2
811 S. First St.
Artesia NM 88210
575-748-1283 Ext 108
mike.bratcher@state.nm.us

From: Blaney, Karolina [mailto:Karolina.Blaney@wpxenergy.com]
Sent: Monday, January 2, 2017 4:17 AM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; stucker@blm.gov
Subject: RE: WPX Brushy Draw Booster Station - initial C-141

Good morning Crystal,
Attached is the delineation plan for the Brushy Booster spills that occurred in July and November of 2016.
I will proceed with the delineation after I receive your approval.
Thank you and have a great day,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com

From: Weaver, Crystal, EMNRD [<mailto:Crystal.Weaver@state.nm.us>]
Sent: Wednesday, December 07, 2016 3:36 PM
To: Blaney, Karolina <Karolina.Blaney@wpenergy.com>
Cc: Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; stucker@blm.gov
Subject: RE: WPX Brushy Draw Booster Station - initial C-141

RE: WPX Energy Inc. * Brushy Draw Booster Station Fed. UCBHWW 1 * 2RP-4011

Hello Karolina,

Attached are the Conditions of Approval for this C-141 Remediation Permit. The OCD tracking number for this event is 2RP-4011.

Thank you,

Crystal Weaver

Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283
Fax: 575-748-9720

From: Patterson, Heather, EMNRD
Sent: Wednesday, December 7, 2016 11:50 AM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Subject: FW: WPX Brushy Draw Booster Station - initial C-141

From: Blaney, Karolina [<mailto:Karolina.Blaney@wpenergy.com>]
Sent: Monday, November 28, 2016 2:09 PM
To: Patterson, Heather, EMNRD <Heather.Patterson@state.nm.us>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: RE: WPX Brushy Draw Booster Station - initial C-141

Attached is the initial C-141 for this spill.
Please let me know if you have any questions or suggestions.
Thank you,

Karolina Blaney
Environmental Specialist
WPX Energy
Office: (575) 885-7514
Cell: (970) 589-0743
karolina.blaney@wpenergy.com

From: Blaney, Karolina
Sent: Monday, November 14, 2016 1:02 PM
To: 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: WPX Brushy Draw Booster Station - spill notification

Good afternoon,

Yesterday, 11/13/16, WPX had a produced water spill at the Brushy Booster Station location. The cause of this spill is equipment failure; a cross arm on an electric failed which cut off power supply to the water transfer pump. Additionally, the ESC float got stuck and didn't trigger the high water alarm notification and didn't shut in the system. Approximately 200 bbls of produced water and stormwater were recovered from the secondary containment (estimated at least 80 bbls of stormwater).

The Brushy Booster Station is located south of the Fed UCBHWW 1, API # 30- 015-24034, qtr/qtr M, S25, T26S, R29E.

The C-141 report will be submitted within 15 days from the incident.

Please let me know if you have any questions or concerns.

Thank you and have a great day,

Karolina Blaney
Environmental Specialist
WPX Energy
Cell: (970) 589-0743
karolina.blaney@wpxenergy.com