

Bratcher, Mike, EMNRD

From: Aaron Pachlhofer <aaronp@forl.com>
Sent: Tuesday, March 28, 2017 2:57 PM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD; stucker@blm.gov
Subject: Fasken El Paso Federal No. 12
Attachments: 1873_001.pdf; 20170327_095937.jpg; 20170327_095939.jpg; 20170327_100017.jpg

Follow Up Flag: Follow up
Flag Status: Completed

Crystal, Mike, and Shelley,

Please find attached the C-141 for the spill/oil theft that occurred this past Saturday, 3/25/17.

As noted on the C-141, there is a very small affected area inside of the firewall with a 'streak' going over the firewall and onto the pad area. Please see attached photos.

My plan at this time is to remove the affected soils from inside the firewall and also the berm and pad area. Since this is an active tank battery, affected soils will be removed to the maximum practicable extent so that the tanks are not undermined. The goal for affected soil on the berm on the pad is total removal.

Following removal, the removed soil will be stockpiled on plastic sheeting and allowed to naturally attenuate. Once the oil has attenuated, our personnel will reuse the soil to reinforce the firewall.

If you have any questions or comments, please let me know, I have a crew beginning work about 9:00 a.m. on 3/30/17. I expect that work will require less than one day.

Finally, I plan to collect one sample inside the firewall and one outside the firewall. It would be great if OCD or BLM was present on Thursday to discuss sample locations.

Thanks,



Aaron Pachlhofer, P.G.
Environmental Coordinator
Fasken Oil and Ranch, Ltd.
6101 Holiday Hill Road
Midland, TX 79707
432-687-1777 Office
830-377-9190 Cell