

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1726252637

#### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID # 229137	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Dump Yard 2 State #001H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No. 30-15-42433
----------------------	----------------------	---------------------

#### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	02	21S	28E	190	South	660	West	Eddy

Latitude 32.5025635 Longitude -104.0637207

#### NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 22 bbl.	Volume Recovered: 20 bbl.
Source of Release: Check Valve on water line	Date and Hour of Occurrence: September 12, 2017 9:00 am	Date and Hour of Discovery: September 12, 2017 9:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

The release was due to a hole on a check valve on the water line going from the FWKO to the water tank. The check valve was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The release was contained within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment was pressure washed to remove any residue from the release. The lined containment was inspected and found to be structurally sound

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Sheldon L. Hitchcock	Approved by Environmental Specialist: 		
Title: HSE Coordinator	Approval Date: 10/30/17	Expiration Date: N/A	
E-mail Address: slhitchcock@concho.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: October 20, 2017	Phone: 575-748-0233		FINAL

\* Attach Additional Sheets If Necessary

2RP-4389