

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC OGRID# [217955]	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: DIAMONDBACK 22 STATE COM #003H	Facility Type: Tank Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-39861
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 22	Township 26S	Range 28E	Feet from the 550	North/South Line North	Feet from the 660	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	------------------------------	----------------------	------------------------	----------------

Latitude 32.0337791

Longitude -104.0685806 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10 bbls PW	Volume Recovered: 8 bbls PW
Source of Release: Fittings and Connections	Date and Hour of Occurrence: 10/5/2017 1:00 P.M.	Date and Hour of Discovery: 10/5/2017 1:00 P.M.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This release occurred when a hole developed in the 4 inch steel nipple on the free water knock out. The corroded nipple was replaced with a stainless steel nipple.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. A final inspection has been conducted regarding the clean-up efforts. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Dakota Neel	Approved by Environmental Specialist:		
Title: HSE Coordinator	Approval Date:	Expiration Date:	
E-mail Address: dneel2@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: November 2, 2017	Phone: 575-746-2010		

* Attach Additional Sheets If Necessary